



## TO ALL IBI CUSTOMERS

### NEW PRODUCT AVAILABLE

The following parts are available for immediate shipment. You will find the IBI No., Description, Application information, FMSI No., and the Parts List listed below. Illustrations are included at the end of the bulletin.

<b>IBI No.</b>	<b>Description</b>	<b>Application</b>	<b>FMSI</b>	<b>Parts List</b>
7885	PISTON-PHENOLIC	2009 Dodge Ram 2500 .(R) 2009 Dodge Ram 3500 SRW.(R)	D1400	1364
7886	PISTON-PHENOLIC	2009 Dodge Ram 3500 DRW.(R)	D1400	1365
24152	BOLT	2008 Dodge Truck Ram Series 4500, 5500 (FR)	D1335	1309
24217	CLIP-PAD LOCATING	2010 Toyota Sequoia (R) 2010-07 Toyota Tundra .(R) 2010-08 Toyota Landcruiser .(R)	D1304	1232, 1332
24217N	CLIP-PAD LOCATING (NiZn)	2010 Toyota Sequoia (R) 2010-07 Toyota Tundra .(R) 2010-08 Toyota Landcruiser .(R)	D1304	1232, 1332
24217Q	CLIP-PAD LOCATING (COATED)	2010 Toyota Sequoia (R) 2010-07 Toyota Tundra .(R) 2010-08 Toyota Landcruiser .(R)	D1304	1232, 1332
24218	CLIP-PAD LOCATING	2010 Toyota Sequoia (R) 2010-07 Toyota Tundra .(R) 2010-08 Toyota Landcruiser .(R)	D1304	1232, 1332
24218N	CLIP-PAD LOCATING (NiZn)	2010 Toyota Sequoia (R) 2010-07 Toyota Tundra .(R) 2010-08 Toyota Landcruiser .(R)	D1304	1232, 1332
24218Q	CLIP-PAD LOCATING (COATED)	2010 Toyota Sequoia (R) 2010-07 Toyota Tundra .(R) 2010-08 Toyota Landcruiser .(R)	D1304	1232, 1332
24251	SEAL-SQ CUT	2008-07 GM Truck Escalada, Avalanche, Sierra Deanli, Silverado, Yukon Denali, Suburban, Tahoe (First Design) (F) 2007-06 Sierra Deanli, C-1500, K-1500 (F)	D1363 D1092	1100

<b>IBI No.</b>	<b>Description</b>	<b>Application</b>	<b>FMSI</b>	<b>Parts List</b>
24268	CLIP-PAD LOCATING	2010-09 Toyota Venza .(R)	D1402	1370
24268N	CLIP-PAD LOCATING (NiZn)	2010-09 Toyota Venza .(R)	D1402	1370
24268Q	CLIP-PAD LOCATING (COATED)	2010-09 Toyota Venza .(R)	D1402	1370
24269	CLIP-PAD LOCATING	2010-09 Toyota Venza (F)	D1401	1369
24269N	CLIP-PAD LOCATING (NiZn)	2010-09 Toyota Venza (F)	D1401	1369
24269Q	CLIP-PAD LOCATING (COATED)	2010-09 Toyota Venza (F)	D1401	1369
24289	BOOT	2010-09 Toyota Venza (R)	D1402	1370
24290	PIN BOOT	2010-09 Toyota Venza (F) 2010-09 Toyota Venza .(R)	D1401 D1402	1369 1370
24311	LOCK BOLT	2010 Mercedes GLK 350 (F)	D1406	1424
24342	BOLT	REPLACEMENT FOR 22599		
24345	SUPPORT SPRING	2009-08 BMW M3 .(R) 2009-06 BMW M5 .(R) 2009-06 BMW M6 .(R)	D919	1430, 1446
24346	PIN BOOT	2010-09 Hyundai Elantra Touring (F-R) 2010 Kia Forte (F) 2010 Hyundai Tucson (F)	D1397 D1398 D1295 D1447	1402, 1403, 1411. 1412, 1442, 1443
24353	CLIP-PAD LOCATING	2009-05 LandRover LR3 (F) 2009-06 Range Rover Sport (F) 2009-06 Range Rover (F)	D1098	1404
24353N	CLIP-PAD LOCATING (NiZn)	2009-05 LandRover LR3 (F) 2009-06 Range Rover Sport (F) 2009-06 Range Rover (F)	D1098	1404
24353Q	CLIP-PAD LOCATING (COATED)	2009-05 LandRover LR3 (F) 2009-06 Range Rover Sport (F) 2009-06 Range Rover (F)	D1098	1404

<b>IBI No.</b>	<b>Description</b>	<b>Application</b>	<b>FMSI</b>	<b>Parts List</b>
24354	CLIP-PAD LOCATING	2009-05 LandRover LR3 (R) 2009-06 Range Rover Sport (R) 2009-06 Range Rover (R)	D1099	1405
24354N	CLIP-PAD LOCATING (NiZn)	2009-05 LandRover LR3 (R) 2009-06 Range Rover Sport (R) 2009-06 Range Rover (R)	D1099	1405
24354Q	CLIP-PAD LOCATING (COATED)	2009-05 LandRover LR3 (R) 2009-06 Range Rover Sport (R) 2009-06 Range Rover (R)	D1099	1405
24361	SPRING-PAD SPREADER WF	2010 Toyota Prius (R)	D1423	1428
24363	SEAL-SQ. CUT	2010 Hyundai Genesis (F) 17" Wheels	D1413	
24373	SEAL-SQ. CUT	2010-03 Hino 145, 165, 185 series (FR)	D1062	1425
24374	GUIDE PIN	2010 Mercedes GLK 350 (F)	D1406	1424
24383	SPREADER SPRING	Mercedes Benz	D145	392
24384	CALIPER PIN	Mercedes Benz	D145	392

### **OBSOLETE**

The following parts are now obsolete and no longer available. Please mark your records accordingly.

4437 Anti Rattle Clip

20502 - Sq Cut Seal

### **SUPERSESSIONS**

13200 - Hardware Kit is now available as individual components.

- 24384 - Caliper Pin and 24383 Spreader Spring

22599 - Bolt has been superseded by 24342

.- This affects parts lists: 632, 816, 934, 935, 936, 1005, 1052, 1118, 1134, 1152, 1180, 1181, 1191, 1200, 1201, 1222, 1228, 1273, 1283, 1289, 1315, 1334, 1336, 1338, 1339, 1381, 1440


23338 – Caliper Support Spring has been superseded by 24345.

- This affects parts lists: 527, 712, 1115, 1368, 1391 and 1393.


We thank you for your continued business and if you have any questions, please contact us.

July 2010


# IBI'S NEW PRODUCTS




24152 – Dodge Truck  
D1335 Quantity per wheel: 1




24217, 24217N and 24217Q  
Toyota D1304  
Quantity per wheel: 2




24218, 24218N and 24218Q  
Toyota D1304  
Quantity per wheel: 2




24268, 24268N and 24268Q –  
Toyota D1402  
Quantity per wheel: 2




24269, 24269N and 24269Q –  
Toyota D1401  
Quantity per wheel: 2



24289 – Toyota D1402  
Quantity per wheel: 1




24290 – Toyota D1401, D1402  
Quantity per wheel: 2




24311 – Mercedes D1406  
Quantity per wheel: 2

International Brake Industries, Inc.  
1840 McCullough, Lima, Ohio 45801


Phone: (419) 227-4421 (800) 537-2838  
\*Illustrations not to scale.




24342 Replacement for 22599  
Quantity per wheel: 2




24345 – BMW D919  
Quantity per wheel: 1




24346 – Hyundai, Kia  
D1295, D1397, D1398, D1447  
Quantity per wheel: 2




24353, 24353N and 24353Q –  
LandRover D1098  
Quantity per wheel: 2




24354, 24354N and 24354Q –  
LandRover D1099  
Quantity per wheel: 2




24361 – Toyota D1423  
Quantity per wheel 1



24374 – Mercedes D1406  
Quantity per wheel 2



24383 – Mercedes Benz  
D145 Quantity per wheel: 1



24384 – Mercedes Benz D145  
Quantity per wheel: 2

International Brake Industries, Inc.  
1840 McCullough, Lima, Ohio 45801  
(419) 227-4421 (800) 537-2838

\*Illustrations not to scale.

**IBI'S NEW PRODUCTS**